

PRODUCT INFORMATION	TYPE OF PRODUCT	Upholstery
	COMPANY NAME	Carnegie by Trevira
	PRODUCT/COLLECTION NAME	Varies
	DESCRIPTION	Fire-retardant upholstery
MATERIAL FEEDSTOCK	MATERIAL CONTENT	100% Polyester
	RECYCLED CONTENT %	None
	RAPIDLY RENEWABLE CONTENT %	No
	HARMFUL ADDITIVES	None added Fire retardance is inherent to the material, so no further treatment is required
	HARMFUL EMISSIONS	Yes – an unknown amount
	EMISSION STRENGTH OVER TIME	Not measured
	TREATMENTS	Some staple fiber products do contain small amounts of spin finish and texturing oil
	MANUFACTURING	MANUFACTURING PROCESS
HARMFUL EMISSIONS		Yes, however, during a fire these amounts will not increase
LOCATION OF MANUF. PLANT		Germany
TESTS/CODES		DIN 4102 Part 1/B1; NF P 92503-507/M1; BS 5867, Part 2 Type C; UNI VF 8456/8457/1; EN 1021 Part 1 + 2 and EN 13772 + 13 773 Class 1 Dimensionally stable Oeko-Tex Standard 100 REACH ISO 9001 : 2000 and ISO 14001 : 2004 UFAC; California TB 116; California TB 133; BOF 14-1; NFPA 701
3RD PARTY CERTIFICATION		Carpet and Rug Industry: Green Label certification, Green Seal, EcoLogo, GreenStar, GreenGuard,
INSTALLATION	INSTALLATION PROCEDURE	Sewn and stapled
	INSTALLATION ADHESIVES	None used
	UNIT COST	A
	LIFE CYCLE ANALYSIS EXTRACTION	What are the financial costs for the material? Is the product energy efficient?
	END OF SERVICE LIFE	Non-recyclable, cannot be incinerated
MISC. PROPERTIES	QUALITIES/PROPERTIES OF PRODUCT	Highly durable
	MISC. COMMENTS	In settings where stringent fire codes must be met, Trevira is a good choice since it is permanently fire retardant and releases far fewer harmful gases when burned than traditional applied fire retardant treatments.
	CONTRIBUTION TO LEED POINTS	None
COMPANY PROFILE	GREEN PHILOSOPHY	One company can make a difference. Leading by example we hope others will think critically about the materials we design and use. Doing the right thing can have a snowball effect.
	CONTACT	Rob Cason Furniture Marketing of the Carolias 14115 Bramborough rd Huntersville, NC 28078 704.651.6101
MAINTENANCE	AFTER INSTALLATION	Short wash at low temperature