PROPUCT	TYPE OF PRODUCT	Finishes
PRODUCT INFORMATION	TYPE OF PRODUCT	Finishes
IN CHIMATION	COMPANY NAME	Anzea
	PRODUCT/COLLECTION NAME	Checkerboard Squares
	DESCRIPTION	Finish: Graffiti-Free
MATERIAL FEEDSTOCK	MATERIAL CONTENT	100% Polyurethane with Polyester Knit Backing
MATERIAL LEBOTOOK	RECYCLED CONTENT %	NA
	RAPIDLY RENEWABLE CONTENT	NA
	%	
	HARMFUL ADDITIVES	NA
	HARMFUL EMISSIONS	None
	EMISSION STRENGTH OVER TIME	None
	TREATMENTS	NA
MANUFACTURING	MANUFACTURING PROCESS	NA NA
<u>marter actorinte</u>	HARMFUL EMISSIONS	None
	LOCATION OF MANUF. PLANT	Korea
	TESTS/CODES	Flammability:
		CAL 117, NFPA 260
		Upholstery
		California Technical Bulletin #117 Section E - Class 1 (Pass)
		Direct Glue Wall coverings and Adhered Panels
		ASTM E 84 (Adhered Mounting Method) - Class A or Class 1
		Wrapped Panels and Upholstered Walls
		ASTM E 84 (Unadhered Mounting Method) - Class A or Class 1
		Drapery
		NEDA TOL D
	o ^{BD} DADTY OF DTIFICATION	NFPA 701- Pass
INICTALLATION	3 RD PARTY CERTIFICATION	NA NA
INSTALLATION	INSTALLATION PROCEDURE	NA NA
	INSTALLATION ADHESIVES	NA Market
	UNIT COST	\$12/yd
	LIFE CYCLE ANALYSIS	The product is energy efficient
	EXTRACTION	Last for every Everade 400 000 devible with (Mirrorheal)
MICC PROPERTIES	END OF SERVICE LIFE	Last for ever; Exceeds 100,000 double rubs (Wyzenbeek)
MISC. PROPERTIES	QUALITIES/PROPERTIES OF	Light fastness: 400 hours
	PRODUCT MISC. COMMENTS	Width: 54"
	WIIGO. COMMENTS	Repeat: .25"H/.25"V
		Weight: 20 oz/linear yard
	CONTRIBUTION TO LEED POINTS	NA
	TOTAL TO LEED TO MITO	NA NA
COMPANY PROFILE	GREEN PHILOSOPHY	
SOME ANT THE TELE	CONTACT	901 Foch Street
		Fort Worth, TX 76107
		Phone: 817.336.2310
		Fax: 817.336.9548
		Email: customerservice@anzea.com
MAINTENANCE	AFTER INSTALLATION	W (water based cleaners): To prevent overall soiling, frequent vacuuming
		or light brushing to remove dust and grime is recommended. Spot clean
		using the foam only from a water-based cleaning agent such as a mild
		detergent or non-solvent upholstery shampoo. Apply foam with a soft rag
		or brush in a circular motion. Vacuum when dry. Always pretest a small
		area before proceeding.